

ASBESTOS MATERIALS ASSESSMENT
BUILDING 49 East Wing 12/2/2020

FLOOR	FUNCTIONAL SPACE/ROOM	HOMOGENEOUS MATERIAL	MATERIAL	MATL.TYPE	QUANTITY	HEIGHT (FEET)	CONDITION	AHERA CATEGORY
BSMT	Room 12	9,10	Floor Tile and Mastic	MISC	40 SF	0	Good	NF
BSMT	Room 12	60	2'x4' Ceiling Panel	MISC	55 SF	8	Good	5
BSMT	Room 13	56	Mastic Under Carpet	MISC	112 SF	0	Good	NF
BSMT	Room 14	56	Mastic Under Carpet	MISC	65 SF	0	Good	NF
BSMT	Room 14A	9,10	Floor Tile & Mastic Under Carpet	MISC	160 SF	0	Good	NF
BSMT	Room 14B	56	Mastic Under Carpet	MISC	96 SF	0	Good	NF
BSMT	Room 15	9,10	Floor Tile & Mastic Under Carpet	MISC	275 SF	0	Good	NF
BSMT	Room 15	20	Pipe Insulation Behind Plaster Wall	TSI	20 LF*4 ftgs	0-11	Good	5
BSMT	Room 16	20	Pipe Insulation Behind Plaster Wall	TSI	20 LF*4 ftgs	0-11	Good	5
BSMT	Room 18	60	2'x4' Ceiling Panel	MISC	110 SF	8	Good	5
BSMT	Room 19	60	2'x4' Ceiling Panel	MISC	110 SF	8	Good	5
BSMT	Room 20	60	2'x4' Ceiling Panel	MISC	110 SF	8	Good	5
BSMT	Room 21	60	2'x4' Ceiling Panel	MISC	110 SF	8	Good	5
BSMT	Room 22	60	2'x4' Ceiling Panel	MISC	120 SF	8	Good	5
BSMT	Room 23	60	2'x4' Ceiling Panel	MISC	120 SF	8	Good	5
BSMT	Room 23	54,55	Mastic Under Carpet	MISC	120 SF	0	Good	NF
BSMT	Room 24	60	2'x4' Ceiling Panel	MISC	120 SF	8	Good	5
BSMT	Room 24	54,55	Mastic Under Carpet	MISC	120 SF	0	Good	NF
BSMT	Room 25	60	2'x4' Ceiling Panel	MISC	120 SF	8	Good	5
BSMT	Room 25A	60	2'x4' Ceiling Panel	MISC	8 SF	8	Good	5
BSMT	Room 26	60	2'x4' Ceiling Panel	MISC	120 SF	8	Good	5
BSMT	Room 26A	60	2'x4' Ceiling Panel	MISC	8 SF	8	Good	5
BSMT	Room 27	60	2'x4' Ceiling Panel	MISC	100 SF	8	Good	5
BSMT	Room 28	60	2'x4' Ceiling Panel	MISC	70 SF	8	Good	5
BSMT	Room 29	60	2'x4' Ceiling Panel	MISC	120 SF	8	Good	5