

Appendix A: Access Point/Conduit Installation Checklist

Bldg.	Floor	Area	Issue to be Addressed
40	1	101	VA to provide conduit pathway from IT closet 102 to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated vertically on wall at AP05 location for room containing hard ceiling
40	1	102A	VA to provide conduit pathway from IT closet 102 to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated vertically on wall at AP06 location for room containing hard ceiling
46	B	We propose moving AP01 26' right to meet VA-ENT requirements. This is a wooden header ceiling type.	VA to provide conduit pathway from IT closet B100 to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP01 location for room containing hard ceiling
46	B	We propose moving AP05 7' up and 21' left to meet VA-ENT requirements. This is a wooden header ceiling type.	VA to provide conduit pathway from IT closet B100 to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP05 location for room containing hard ceiling

Bldg.	Floor	Area	Issue to be Addressed
46	B	B103	VA to provide conduit pathway from IT closet B100 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP08 location for room containing hard ceiling
46	1	We propose moving AP06 34' up to meet VA-ENT requirements.	VA to provide conduit pathway from IT closet B46-FB-B100 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP06 location for room containing hard ceiling
46	2	We propose moving AP02 84' right and 17' down to meet VA-ENT requirements.	VA to provide conduit pathway from IT closet B46-FB-B100 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP02 location for room containing hard ceiling
46	2	We propose moving AP04 50' left and 5' down to meet VA-ENT requirements.	VA to provide conduit pathway from IT closet B46-FB-B100 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP04 location for room containing hard ceiling

Bldg.	Floor	Area	Issue to be Addressed
48	B	B100	VA to provide conduit pathway from IT closet B110-F1-105A to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP03 location for room containing hard ceiling
48	1	100B	VA to provide conduit pathway from IT closet B110-F1-105A to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated vertically on wall at AP05 location for room containing hard ceiling
48	1	Outside of Room 103	VA to provide conduit pathway from IT closet B110-F1-105A to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP06 location for room containing hard ceiling
48	1	102	VA to provide conduit pathway from IT closet B110-F1-105A to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP07 location for room containing hard ceiling

Bldg.	Floor	Area	Issue to be Addressed
53	B	B100A1	VA to provide conduit pathway from IT closet B108 to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP07 location for room containing hard ceiling
53	B	B102	VA to provide conduit pathway from IT closet B108 to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP08 location for room containing hard ceiling
85	1	101	VA to provide conduit pathway from 106 to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP03 location for room containing hard ceiling
88	1	B101C	VA to provide conduit pathway from IT closet 100A to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP09 location for room containing hard ceiling
89	1	111	VA to provide conduit pathway from IT closet B89-F2-200 to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP05 location for room containing hard ceiling

Bldg.	Floor	Area	Issue to be Addressed
110	1	104	VA to provide conduit pathway from IT closet 105A to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP07 location for room containing hard ceiling
110	1	103A	VA to provide conduit pathway from IT closet 105A to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP08 location for room containing hard ceiling
110	1	102	VA to provide conduit pathway from IT closet 105A to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP09 location for room containing hard ceiling
113	B	B02A	VA to provide conduit pathway from IT closet TCBA to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated vertically on wall at AP22 location for room containing hard ceiling

Bldg.	Floor	Area	Issue to be Addressed
113	1	CC2-113	VA to provide conduit pathway from IT closet EC1C to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP76 location for room containing hard ceiling
113	1	CC1-146	VA to provide conduit pathway from IT closet EC1C to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP77 location for room containing hard ceiling
144	1	104	VA to provide conduit pathway from IT closet 108 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP01 location for room containing hard ceiling
144	1	109	VA to provide conduit pathway from IT closet 108 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP02 location for room containing hard ceiling
144	1	114	VA to provide conduit pathway from IT closet 108 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP03 location for room containing hard ceiling

Bldg.	Floor	Area	Issue to be Addressed
145	1	130	VA to provide conduit pathway from IT closet TC1A to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP30 location for room containing hard ceiling
145	3	334	VA to provide conduit pathway from IT closet TC3A to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP29 location for room containing hard ceiling
146	1	106D	VA to provide conduit pathway from IT closet 117 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP24 location for room containing hard ceiling
146	1	Hallway 120	VA to provide conduit pathway from IT closet 117 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP26 location for room containing hard ceiling
146	1	121	VA to provide conduit pathway from IT closet 117 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated vertically on wall at AP28 location for room containing hard ceiling

Bldg.	Floor	Area	Issue to be Addressed
147	1	We propose moving AP02 from Hallway outside of 110 to 103 to meet VA-ENT requirements.	VA to provide conduit pathway from IT closet 109 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP02 location for room containing hard ceiling
147	1	104	VA to provide conduit pathway from IT closet 109 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP09 location for room containing hard ceiling

End of SOW