

Appendix A: Access Point/Conduit Installation Checklist

Bldg.	Floor	Area	Issue to be Addressed
46	B	B103	VA to provide conduit pathway from IT closet B100 to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP08 location for room containing hard ceiling
50	1	202	VA to provide conduit pathway from IT closet B101 to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP03 location for room containing hard ceiling
89	1	111	VA to provide conduit pathway from IT closet B89-F2-200 to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated horizontally at AP05 location for room containing hard ceiling
113	B	B02A	VA to provide conduit pathway from IT closet TCBA to designed AP location, in open and hard ceiling area, with 4-11/16" dual gang box situated vertically on wall at AP22 location for room containing hard ceiling

Bldg.	Floor	Area	Issue to be Addressed
113	1	CC2-113	VA to provide conduit pathway from IT closet EC1C to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP76 location for room containing hard ceiling
113	1	CC1-146	VA to provide conduit pathway from IT closet EC1C to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP77 location for room containing hard ceiling
145	1	130	VA to provide conduit pathway from IT closet TC1A to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP30 location for room containing hard ceiling
145	3	334	VA to provide conduit pathway from IT closet TC3A to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP29 location for room containing hard ceiling
146	1	106D	VA to provide conduit pathway from IT closet 117 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP24 location for room containing hard ceiling

Bldg.	Floor	Area	Issue to be Addressed
146	1	Hallway 120	VA to provide conduit pathway from IT closet 117 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP26 location for room containing hard ceiling
146	1	121	VA to provide conduit pathway from IT closet 117 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated vertically on wall at AP28 location for room containing hard ceiling
147	1	We propose moving AP02 from Hallway outside of 110 to 103 to meet VA-ENT requirements.	VA to provide conduit pathway from IT closet 109 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP02 location for room containing hard ceiling
147	1	104	VA to provide conduit pathway from IT closet 109 to designed AP location, in open and hard ceiling area, with 4-11/16” dual gang box situated horizontally at AP09 location for room containing hard ceiling

End of SOW