



Second Floor

Old pipe chase with isolation valves near

Old pipe chase that may have isolation valves, review network

PLAN NOTES:
 ① COULD NOT VERIFY UTILITY ROUTING DUE TO HARD CEILINGS, PIPING IN WALLS, OR INACCESSIBLE AREAS. ANY UTILITY PIPING SHOWN ON PLAN IN THIS GENERAL AREA IS AN ASSUMPTION OR ESTIMATION.

